


15.262.20



The valve is made of EPDM and the handle is covered by PVC, during the long-term UV exposure, they may become deterioration as earlier than general use.